



# NCT-2

## Non-Contacting Tachometer

EQUIPMENT	DESCRIPTIVE	ITEM NUMBER
-----------	-------------	-------------

### Popular Packages (115 VAC)

NCT-2, Nema 4	NCT-2-5-1-1-__	90321000
NCT-2, Nema 4, LCD Meter	NCT-2-5-1-2-__	90321100
NCT-2, Nema 4, Dual Alarm Card	NCT-2-5-1-3-__	90321010
NCT-2, Nema 4, LCD Meter & Dual Alarm Card	NCT-2-5-1-4-__	90321110
NCT-2, Open Style	NCT-2-1-1-1-0	90311000
NCT-2, Open Style, Dual Alarm Card, Backpan Mounted	NCT-2-1-1-3-__	90311010
NCT-2, Nema 4X Stainless	NCT-2-9-1-1-__	90331000
NCT-2, Nema 4X Stainless, LCD Meter	NCT-2-9-1-2-__	90331100
NCT-2, Nema 4X Stainless, Dual Alarm Card	NCT-2-9-1-3-__	90331010
NCT-2, Nema 4X Stainless, LCD Meter & Dual Alarm Card	NCT-2-9-1-3-__	90331110

Add the following suffix for Motion Sensing Probe and Remote Mounted Amplifier (if needed) selection in \_\_\_\_:

MSP-1 (with RMA in Nema 4) (Manufactured by Westec)		7MH7146-0AA + 7MH7145-0A
MSP-12 Low Temperature Probe	1	7MH7146-0EA
MSP-3 High Temperature Probe (with RMA in Nema 4)	2	7MH7146-0BA + 7MH7145-0A
XPP-5 Explosion Proof Probe (with 5 feet of cable)	3	7MH7146-0GA
XPP-5 Explosion Proof Probe (with 30 feet of cable)	4	7MH7146-0HA
MSP-9 304 SS Probe (with RMA in Nema 4 SS)	6	7MH7146-0DA + 7MH7145-0D

### Optional Equipment and Parts

230 Volt Operation	Optional
LCD Meter	51007611
Dual Alarm Card	51007421
RMA Circuit Board	7MH7723-1DT
Fuses, Box of 5, 2/10 Amp, Slo-Blo (For 115 VAC)	22550055
Fuses, Box of 5, 1/10 Amp, Slo-Blo (For 230 VAC)	22550056
Transformer, 30A190, (For 115 VAC)	26350190
Transformer, 30A241, (For 230 VAC)	26350241
Extra NCT-2 Manual	IM-3